

# **Code of Practice**

Highways inspections



Ref	Date	Revision Details	Reviewed By	Approved By
1	April 14	Issued at start of Contract – dated October 2013 – Version 2	Danny Mullins	Andy Dickinson
2	Sept 14	Updated format; added in details regarding Confirm connect as per new contract processes; updated quality control processes; updated note 1 in defect categorisation; updated info required on defect; inclusion of defect codes form confirm; updated tolerance of inspection due dates	Andy Dickinson/ Hannah Shires	Andy Dickinson
3	Dec 14	Clarification of Desire lines, inclusion of Kerb defect tables, inclusion of bollards and potholes in priority criteria, inclusion of laybys in priority hierarchy, inclusion of policy approaches to Snow conditions and high-density defect areas	Andy Dickinson/ Hannah Shires	Andy Dickinson
4	Feb 16	Include defect matrix	Andy Dickinson/ Patrick Connolly	Andy Dickinson
5	November 16	Review Draft Changes – Version 4.2	Andy Dickinson/ Patrick Connolly	Andy Dickinson
6	January 17	Issued Final Copy – Version 4.3 – Dated November 16	Andy Dickinson/ Patrick Connolly	Andy Dickinson
7	March 18	Review Draft Changes – Version 4.4	Andy Dickinson/ Steve Ashley/Patrick Connolly	Andy Dickinson
8	October 18	Amend document following Pothole Review recommendations agreed by cabinet September 2018 – Version 4.5	Andy Dickinson/ Debbie Taylor-Bond	Andy Dickinson
9	February 19	Update defect process flow - Draft	Andy Dickinson	Andy Dickinson
10	April 19	Final Version to include defect process flow – Version 4.6	Andy Dickinson/ Patrick Connolly	Andy Dickinson
11	December 19	Update on bollards (7.2 and 8) following HSE safety alert – Version 4.7	Andy Dickinson	Andy Dickinson
12	March 20	National 'Lockdown' Covid 19 pandemic – Statement Emergency works only – Version 4.7.1	Brian Varney	Andy Dickinson
13	April 20	National 'Lockdown' Covid 19 pandemic – Emergency works, restricted inspections plus enquiry responses only – Version 4.7.2	Brian Varney	Andy Dickinson
14	August 20	Review existing CoP (version 4.7) to implement following lifting of last 'Lockdown' restrictions, increase in enquiries and financial requirements imposed by authority.	D. Smith/ R. Moffoot/Andy Dickinson	Andy Dickinson
15	September 20	Issued reviewed Code of Practice – Version 4.8	D. Smith/ R. Moffoot/Andy Dickinson	Andy Dickinson
16	April 21	Review matrix risk tables and associated definitions – Version 4.9 plus review programming dates	A Dickinson/ D. Smith	Andy Dickinson
17	April 21	Add specifics regarding Bus Shelters. Version 4.9.1	A. Dickinson	Andy Dickinson
18	July 21	Review pothole sections and priorities to include larger patches.	A. Dickinson/ M. MacDonald	Andy Dickinson
19	October 21	Review of prioritisation target dates	M. MacDonald	Andy Dickinson

20	May 22	Inclusion of Visual Risk Assessment Matrix and Update of Asset  Management System – Version 4.9.3 DRAFT	M. MacDonald	Andy Dickinson
		The management of stems in the		
21	July 22	Inclusion of Visual Risk Assessment Matrix and Update of Asset Management System – Version 4.9.3 Final	M. MacDonald	Andy Dickinson
22	January 2023	Review CoP for new Contract – Version 5.0.0 Final	M. MacDonald	Andy Dickinson
23	January 2025	Review CoP for Contract – Version 5.0.1 DRAFT	M.MacDonald	Andy Dickinson
24	April 2025	Confirm updates – Version 5.0.2 Final	M. MacDonald	Andy Dickinson

Title	Code of Practice for Highway Inspections
Current Version Number	5.0.2
Issue Date	April 2025
Document Status	Published
Previous Version	5.0.1
Author/s	Mark MacDonald
Signature / Date	M Mail anul 9.  17th April 2025
Checked By	Andrew Dickinson
Signature / Date	17 <sup>th</sup> April 2025
Date of Next Review	January 2026

### **Contents**

1.	Introduction	5
2.	Definitions and Responsibilities	8
3.	Budgets and Resources	9
4.	Definition of Carriageway and Footway Categories	13
5.	Frequencies of Inspection	14
6.	Quality Control	16
7.	Methodology for Inspections	16
8.	Defects Identified during Safety Inspections	21
9.	Information to be Added to the Defect	28
10.	Defects not under the ownership of the Council	31
12.	Defects – Investigatory Levels	36
	Location	44
13.	Examples of Prioritisation of Defects	47

### 1. Introduction

The Council has a duty to maintain its highways as outlined within Section 41 of the Highways Act 1980. For the purpose of Section 58 of the same, which provides for a special defence, Milton Keynes City Council (MKCC) carries out cyclic highway safety inspections of all its adopted highways.

This Code of Practice has therefore been developed with the primary aim of providing assistance to those carrying out highways safety inspections on behalf of MKCC, in order that they may carry out their duties with consistency and to clearly recognised and understood criteria.

This code has been developed and reviewed by a working group of officers and inspectors who are directly involved at varying levels of responsibility in the function of highway related maintenance, inspections, claims and management. This code gives due regard to the Council's duties and has taken reference from other codes of practice and appropriate legislation.

MKCC's code is based on the "UK Roads Liaison Group Well-Managed Highways Infrastructure Code of Practice for Highways Maintenance Management" (2016) and amendments. This document gives guidance for the delivery of a safe and well-managed highway network relying on good evidence and sound engineering judgement. The intention of this Code is that Authorities will develop their own levels of service, and therefore provides guidance for authorities to consider when developing their approach in accordance with local needs, priorities and affordability. This code makes specific recommendations in Section A.5 'Risk Based Approach' with regard to surveys and inspections using a risk-based approach.

Our methodology is to undertake safety inspections as follows;

- Planned cyclic safety inspections to identify potential hazards proactively.
- Reactive safety inspections following customer enquiries logged in respect of defects reported on the highway.

Records of cyclic safety inspections and reactive safety inspections are maintained on a service specific computer database.

This code sets out investigatory levels and operational processes that are considered appropriate and reasonable, taking into account the safety of highway users and the constraints placed upon the Council to manage public funds responsibly within defined budgets.

Safety inspections are carried out to specified frequencies, dependent upon the hierarchy of each part of the highway in line with the guidance in the Code of Practice for Highway Maintenance Management. During the inspection, defects are identified for investigation

where they meet the investigatory levels as outlined within this code, and jobs are raised, prioritised and processed for repair.

### **Annual review of Code of Practice for Highway Inspections**

This Code of Practice for Highway Inspections is reviewed annually. The review process involves feedback from the Highway Inspectors, a group review in a weekly meeting and then a follow up session once the new code has been adopted to explain the main changes and expectations, and identify any further training requirements.

## Highways Maintenance Efficiency Programme (HMEP) Pothole Review - MK Highways Statement

In April 2011 the Government announced an initiative to review the pothole problem under the umbrella of the Department for Transport sponsored Highways Maintenance Efficiency Programme (HMEP). A Project Board involving a range of key stakeholders from the public and private sectors, including road, footway and cycle user groups was set up in August 2011.

The Review has considered how local highway authorities in England currently deal with potholes, as well as wider stakeholder views and implications. The focus of the Review has been to identify good practice through consultation, and to demonstrate how potholes and other related aspects of highway maintenance may be dealt with more efficiently and effectively. This will also enable sharing of knowledge between authorities, including lessons learnt. MK Highways team contributed to this review.

Following the completion of this review and the publishing of the final document there are three key messages:

- **1. Prevention is better than cure** intervening at the right time will reduce the number of potholes forming and prevent bigger problems later.
- **2. Right first time** do it once and get it right, rather than face continuous bills. Guidance, knowledge, and workmanship are the enablers to this.
- **3.** Clarity for the public local highway authorities need to communicate to the public what is being done and how it is being done.

We have procured and commenced a new term service contract in September 2024, and we have changed the approach within the scope specification for highway repairs requiring a "right first time" approach from the contractor and a minimum 2 year warranty on all repairs to improve quality.

Within the contract the highways repair service has been outlined with the 'Contract Scope' and all maintenance is delivered within Core Service 009 – Routine, Reactive Highway Repairs and Emergencies. The contractor is to provide an effective response to emergencies

and to undertake routine and reactive maintenance on highway assets within appropriate timescales in accordance with the Milton Keynes Code of Practice for Highways Inspections to ensure a safe highway network is maintained.

### 2. Definitions and Responsibilities

### **Definitions**

The Client	Milton Keynes City Council Highways Service Team.
Highways Liaison Team	The Highways Liaison Team provide a support function to the
The Contractor	Highway Inspectors in delivering the inspection service Ringway Infrastructure Services Ltd
Hazard	In the terminology of this document a hazard is defined as an issue or defect on the network that has potential to cause harm to highway users.
Investigatory Level	Depth/size at which a defect is then subject to a risk assessment as to whether it poses a hazard to the highway user.
Defect	In the terminology of this document a defect is defined as a logged defective element of a highways asset and has an associated defect code and priority ranging from below investigatory level to high priority.
Risk matrices for defects and visual risk assessment  Risk matrices that consider the probability and the im defect identified for investigation. Following the risk assessment the defect is assigned a priority and raised as a Works for repair.	
Works Required	In the terminology of this document a Works Required is defined as the action raised from a defect or a hazard that will be completed by the contractor. All works will be completed in accordance with works scheduling process.
Asset Management System – AMX (Asset Management Expert)	The highways asset infrastructure management system that captures all details of hazards, defects, and Works Required.
AMX mobile application	The mobile version of the Asset Management System (AMS) that allows inspections to be carried out electronically on site.

### **Key Responsibilities**

The *Client* has a responsibility to undertake inspections in accordance with this Code of Practice and provide guidance to ensure the contractor has clear instruction to deliver the Highways Repairs Service.

The *Contractor* has a responsibility to deliver the repair service in line with this Code of Practice and achieve the quality standards and objectives (SPI - Service Performance Indicators and KPI – Key Performance Indicators) outlined in the contract scope.

Further responsibilities for other parties are outlined in the detail contained within this Code of Practice.

### 3. Budgets and Resources

To deliver its 'duty of care' to users of the highway, and to ensure best value in public service, the Council provides financial resources to ensure that inspections and operations can be carried out in both a planned and reactive manner to maintain its highway in a safe condition. Clearly, reactive and planned programmes of work to remedy defects are dependent on the resources available to the authority to manage the risks that defects may present. This manual therefore provides guidance on the appropriate identification, assessment, and classification of defects to be repaired; with priority decided following a defect-specific visual risk assessment by the inspector.

### a. Budgets

Each year the Council determines the allocation of its financial resources with due consideration to its strategic aims and priorities. The highway maintenance budget is one area of allocation, which is split into a number of core service delivery areas, each with its dedicated budget. An allocation of budget is specifically set aside for undertaking routine, reactive and emergency repairs identified during all safety inspections.

#### **b.** Resources

A team of competent Highways Inspectors are used to undertake cyclic safety inspections and reactive ad-hoc inspections. This team currently consists of four full time Highway Inspectors. The Highway Inspectors are supported by a line manager to provide guidance, advice and supervision. The Service Manager is also available for guidance and to implement changes to the Code of Practice that need to be contractually communicated. The Highway Inspectors are provided with an electronic tablet to carry out inspections, availability of a Chapter 8 liveried vehicle for driven inspections, and full Personal Protective Equipment in accordance with Health and Safety Policy.

Additional resource in the form of the Highways Liaison Team has been assigned to support the Highways Inspectors. Milton Keynes has been divided into 4 areas, each with a dedicated inspector and liaison officer assigned, to manage highway enquiries, escalations, inspections and complaints.

### c. Competency

Both new and existing Highway Inspectors are required to work remotely and independently when undertaking site inspections, interpret guidance documents, apply codes of practice, identify appropriate repair solutions, understand their role in terms of laws that affect the highway and asset management principles to ensure good management of assets. They are also required to give evidence and represent the Council in line with data they have generated and decisions made.

In order to evidence competency of inspectors we have reviewed the UKRLG 'Highway Inspector Competence Framework' and applied elements of this to our own inspection team. This will assist inspectors' development and ensure consistency in approach and that all inspectors have a minimum level of training and assessed competency.

#### This will include;

- Industry level training
- Internal asset system (AMX) training
- Desk based defect assessment sessions
- Site audits defect assessments
- Training on construction processes and materials
- Weekly inspector team meetings
- Monthly 1 to 1 identifying team objectives/training requirements/skills gaps/actions
- Annual review and training on Code of Practice for Highway Inspections
- Create individual competency statement

Each inspector will hold all training and competency assessment material in the Highways Inspection team folder on Sharepoint. New inspectors will receive additional support during induction and will be subject to a training plan incorporating the above.

### **Industry Level Training**

#### City and Guilds 6033

#### Unit 301, Health and Safety and Unit 311 Highway Safety Inspection

These courses are designed to assess the inspector's ability to work safely on the highway and to provide a qualification that will prove the inspector's knowledge with respect to undertaking safety inspections.

#### NRSWA Supervisors Accreditation (add awarding body)

Inspectors are expected to have, or to attain this accreditation whilst in post. The course can be taken by a day release method, or a one-off week's training course.

#### Lantra T7

Traffic Management course designed to give the Inspector the ability to determine traffic management requirements.

#### **Court Training**

Training to be undertaken in order to expose the inspector to court scenarios and prepare them for the process of a legal court and cross examination by legal counsel.

### **Asset System Training**

Milton Keynes City Council operates a combined works management and asset management system called AMX. This system is used to manage all aspects of the highways service including highway inspections. All inspectors have to attend internal training sessions and have training videos on the use of the councils SharePoint system for reference.

### Desk/Site based Audit Assessments

In order to establish and monitor competency of inspectors MKCC carries out an annual desk-based competency exercise with the inspectors as a group involving defect identification/prioritisation in line with this Code of Practice. In addition the inspectors will also be subject to a site based audit to establish competency in multiple areas.

### **Training on Construction Processes and Materials**

MKCC and its contractor undertake learning through specific training courses to introduce and understand application of different products/ processes the inspectors are always encouraged and expected to attend these courses. Details added to individual 1 to 1 training programmes.

### **Weekly Inspector Team Meetings**

A weekly Inspector team meeting is held with the Highways Liaison team and is chaired by the Highways Service Manager/Asset Engineer. The purpose of this is to plan activities for the following week, confirm resilience cover for leave, and raise any issues encountered during the previous week. It is also an opportunity to communicate areas of open discussion on key issues to enable shared learning such as case law pertaining to highway claims.

### Formal 1 to 1 Staff Appraisals

An appraisal in the form of a one to one is held in accordance with MKCC guidelines, both to provide the appraisee with an opportunity to discuss any training requests, developmental needs, and issues, and for the Manager to talk about performance and any issues related to work.

### New Inspectors Induction Training in addition to the above

### **Managers Introduction and Briefing**

All new members of staff engaged in highway inspections undergo a manager's briefing and introduction on starting. This would include.

- a) A brief overview of the Council and its objectives
- b) A briefing on highway procedures and protocol
- c) A health and safety Induction
- d) An introduction into IT procedures
- e) An induction into the workplace

#### **Work Shadowing**

Dependent on the knowledge and experience of the new inspector, work shadowing can be arranged. This entails 'shadowing' an existing highways inspector to gain first-hand knowledge of procedures and actions taken. No new inspector will be allowed to carry out inspections until he has been assessed as competent and holds the core qualification of C & G 6033 as a minimum.

### **Code of Practice for Highway Inspections**

Any new member of staff will be provided with this document, but also shown the Code of Practices for Highway Maintenance Management, and where it is kept. This document will form the basis of highway inspections for Milton Keynes.

### **IT** courses

These courses are run in-house, and most Microsoft products are covered, i.e., Excel, Word, and Outlook. Courses can be undertaken at all levels from basic to advanced.

### 4. Definition of Carriageway and Footway Categories

Milton Keynes City Council has considered the guidance in 'Well Managed Highway Infrastructure' in terms of local application and developed a road and footway category and hierarchy as shown below.

### a. Carriageways

Category 1	Motorways	None
Category 2	Strategic	All 'A' roads
Category 3a	Main Distributor	Grid roads that are not 'A' roads and 'B' roads within the designated area.
Category 3b	Secondary Distributor	'B' roads outside the designated area & all 'C' roads.
Category 4a	Link Road	Bus service routes
Category 4b	Local Access Road	All other roads

### b. Footways

Category 1a	Prestige Walking Zone	None
Category 1 Primary	Walking Route	All defined Primary Routes
Category 2	Secondary Walking Route	Local Centres and other shopping areas. Other CMK areas
Category 3	Link Footways	School main entrances
Category 4	Local Access Footways	All other footways
Category 5	Public Rights of Way	

### c. Redways (Cycleways)

	· · · · · · · · · · · · · · · · · · ·	
Category a	Cycleways that form part of the carriageway	
Category b1	Primary redways, identified in salting routes	
Category b2	All other redways	
Category c	Leisure Routes – not normally MK responsibility	

### d. Laybys & Car Parks on adopted highway

To be treated as Carriageway Category that the layby or car park is attached to and shall be inspected as part of that inspection frequency. Inspectors may vary the priority of a defect repair in a layby or car park based on Table 3 (Visual Risk Assessment) if they consider that it presents a greater risk to pedestrians.

### 5. Frequencies of Inspection

All highways are assigned a frequency of inspection that can vary dependent upon a number of factors, including:

- Classification of road
- Amount of pedestrian traffic
- Location

A particular highway may in some instances have varying frequencies of inspections along its length.

Safety Inspections must be completed within a tolerance of +/- 5 calendar days of their scheduled date. The Service Manager may alter the due date of a Safety Inspection for operational reasons, but any such alteration will be subject to a documented risk assessment.

Compliance with the required frequencies is monitored at a corporate level by MKCC's Quarterly Performance Data report.

These categories and priority for inspection are reviewed annually in order to take into account changes of use, new infrastructure in existing streets, and adopted areas as a result of development. This review will be undertaken by the Asset team and recorded changes added to the AMX system which will then be adopted as the new inspection regime.

The general frequencies are as follows:

### a. Carriageways

Category	Frequency	Method of Inspection
Category 2	Monthly	Driven
Category 3a	3 Monthly	Driven
Category 3b	3 Monthly	Driven
Category 4a	6 Monthly	Driven
Category 4b	Annually	Urban - Walked in conjunction with the footway inspections. Rural - Driven See Note A

Note A: for serviceability inspections all driven inspections shall be undertaken with a recordable AI system in the vehicle.

### b. Footways

Category	Frequency	Method of Inspection
Category 1	Monthly	Walked
Category 2 Others	3 Monthly	Walked
Category 2 CMK	4 Monthly	Walked
Category 3	6 Monthly	Walked
Category 4	Annually	Walked

### c. Redways

Category	Frequency	Method of Inspection
Category b1	6 monthly	Walked/Cycled
Category b2	Annually	Walked/Cycled

### 6. Quality Control

Quality Audits on the defects and jobs raised during an inspection will be undertaken throughout the year by MKCC line manager in line with competency assessments.

### 7. Methodology for Inspections

### a. Method of carrying out Inspections

The inspections for both footways and carriageways in Central Milton Keynes, town centres, estates and rural footpaths are undertaken on foot.

Each Highways Inspector is responsible for a dedicated area within Milton Keynes, with the aim of improving efficiency and consistency through local knowledge. Where operationally possible, all cyclical and reactive inspections within the dedicated area will be carried out by the same Highways Inspector.

Principal roads, classified roads, bus routes, grid roads and rural unclassified roads are driven. All driven inspections are carried out by two persons – a driver and a dedicated observer. The observer will always be a competent Highways Inspector, and all Inspectors are expected to carry out this function on a rota basis.

See Note A – Section 5a – Carriageways.

Redways are either cycled or walked.

### b. System recording of Inspections

Inspection information is entered onto electronic data capturing equipment (tablet). These devices are set up with the AMX system and are continually synchronized with the 'host' system for processing throughout the day. Inspections are undertaken with due regard to staff safety and in accordance with the appropriate procedures.

During the inspections, the Highways Inspectors add defects in accordance with the defect codes available using the mapping functions on AMX (Table 1 – Defect Codes – Page 22 & 23). Priority codes are then added to the defects by the Highways Inspectors in accordance with the guidance contained in this Code of Practice. Photographs are taken of each defect raised to help show location and severity of the defect. These are all stored and accessible in AMX.

Reactive Inspections as a result of an enquiry are sent to the appropriate Highways Inspector who is inspecting the relevant area. It will appear on AMX Mobile as an "enquiry" and the

Highways Inspector will respond appropriately by either closing down the enquiry with appropriate information and photograph, or raise a defect associated with the enquiry. In some circumstances they may need to be referred to a third party and if this is the case then they will still capture as much information on site as possible.

### 7.1 Risk Management of Defects

In accordance with the new national guidance on risk management of the highway assets, MKCC has updated this code of practice for highway inspections to adopt the investigatory principle that replaces the intervention level. This is the primary change to the document and requires the highway inspector to apply a judgement using the risk matrix tables rather than only taking action when a defect reaches a set trigger. This is to ensure all risk factors are taken into consideration and all defects are given the appropriate repair priority in accordance with the risk assessment. Section 12 indicates investigatory levels used to trigger a visual risk assessment which is then carried out in accordance with table 3.

### 7.2 Investigatory level

The investigatory level is the point at which a risk assessment should be conducted. It must be stressed that these investigatory levels are for purposes of guidance **only**, and that in particular circumstances, inspection items with a lesser degree of deficiency, may pose an equal or greater safety hazard. Note: this is a visual risk assessment (VRA) see table 3.

A Highway Inspector's on-site judgement will always need to take an account of the circumstances that prevail. For example, the degree of risk from a pothole depends upon not only its depth, but also on its surface area and location, and as such may warrant differing response times. When a defect is imminently approaching, has reached, or is in excess of the investigatory level, the highway inspector should conduct a VRA in order to determine the appropriate level of response. See table 3.

The following steps should be used to determine what action, if any should be taken when a defect is identified during an inspection.

- a) **Risk Identification:** As stated previously, this is any inspection item with a defect level that is imminently approaching, has reached, or is in excess of the stated defect investigatory level in the risk matrix tables Section 12.
- b) **Risk Evaluation:** All identified risks have to be evaluated in terms of their significance, which means assessing the likely impact should the risk occur and the probability of it actually happening. See table 3.
- c) Risk Impact/Probability: The impact is quantified by assessing the extent of damage likely to be caused should the risk become an incident. As the impact is likely to increase with increasing speed, the amount of traffic and type of road are clearly

important considerations in the assessment. The probability is quantified by assessing the likelihood of users, passing by or over the defect, encountering the risk. As the probability is likely to increase with increasing vehicular or pedestrian flow, the network hierarchy and defect location are, consequently, important considerations in the assessment. Examples are shown in the tables on the next page. Note this list are examples only, and do not cover all impacts or probabilities possible during the VRA. See table 3.

Defect	Impact Risk – factors to consider
Users	<ul> <li>Type of user i.e., vehicles/pedestrians/cyclists/wheelchairs</li> <li>Shared surfaces e.g., Redways or CMK Underpasses can be used by pedestrians and cyclists and have differing risks</li> <li>Vulnerable users – Wheelchairs, visually impaired, prams/buggies, the elderly</li> <li>Electric Scooters – These are being trialled in MK from 2020, pending review and legalisation</li> </ul>
Trips/gaps/rocking slabs	<ul> <li>Damage to clothing</li> <li>Sprained ankles</li> <li>Broken wrists, arms etc</li> <li>Complications to elderly could be serious</li> </ul>
Potholes	<ul> <li>Damage to car tyres, wheels etc</li> <li>Loss of control and serious or fatal injury</li> <li>Risk to cyclists/motorcyclists is higher</li> <li>Structural damage (bridge surface/joints)</li> </ul>
Poor surface friction	Skidding, serious injuries or fatalities owing to extreme deceleration from high speeds or crushing owing to side impact.
Missing/ Damaged Street Furniture/Bus Shelters	<ul> <li>Road Traffic Collisions/impact with traffic islands</li> <li>Uncontrolled pedestrians crossing carriageway leading to serious injury</li> <li>Damaged bollard falling and causing injury</li> <li>Pedestrian injury caused by defective elements on Bus Shelters</li> <li>Vehicle Restraint System/Bridge Parapets</li> </ul>
Standing Water	<ul> <li>Aquaplaning can occur at speeds above 40 mph. Serious injuries or fatalities owing to extreme deceleration from high speeds or crushing due to side impact. See Code of Practice for Drainage Maintenance</li> </ul>
Obstructions	<ul> <li>Any obstruction on the highway has the possibility to impact any highway user ranging from trips for pedestrians to impact collision for vehicles/motorcycles, ranging from minor to serious or fatal.</li> </ul>

Defect	Probability – factors to consider					
Users	<ul> <li>Certain defect types may affect wheeled transport such as cycles/scooters i.e., gaps in modules/slabs and will have higher risk to that user group</li> <li>Visually impaired/wheelchair users will be affected to a higher degree by obstructions</li> </ul>					
Trips/gaps/ rocking slabs	<ul> <li>High footfall pedestrianised area</li> <li>Category of footway</li> <li>Major pedestrian route for events</li> <li>Route to school</li> <li>Vicinity to vulnerable users</li> </ul>					
Potholes	<ul> <li>Category of carriageway</li> <li>Location of defect on carriageway e.g., wheel track/roundabout</li> <li>Size of defect i.e., overall dimension/delamination &gt;300mm</li> <li>Highly trafficked route</li> <li>Adjacent to ironwork exposing metal edges</li> </ul>					
Poor surface friction	<ul><li>Category of carriageway</li><li>Location e.g., bend/braking area/junction</li></ul>					
Missing/Damaged Street Furniture/Bus Shelter	<ul> <li>Approaches to roundabouts/junctions in high category carriageways/car parks/service roads</li> <li>Controlled crossing points near high use pedestrianised areas</li> <li>Bus Shelter structure used by pedestrians</li> </ul>					
Standing Water See Code of Practice for Drainage Maintenance	<ul> <li>Category of carriageway</li> <li>Speed of carriageway</li> <li>Location on carriageway e.g., bend/junction</li> </ul>					
Obstructions	<ul> <li>Category of footway/carriageway i.e., use/speed</li> <li>Location of obstruction e.g., in middle of footway, on bend</li> <li>Size of obstruction and impact on users</li> </ul>					

### d) Risk Matrices

Actionable repairs identified during safety inspections fall into five categories (see table 2 – Defect Categorisation – page 30) each defect will be visually risk assessed (see table 3) and will be given a time category for repair if appropriate.

The categories directly relate to the considered degree of danger presented by a defect following the visual risk assessment (see table 3), and as such the timescale for repair to remove the identified risk to the highway user.

This is defined in more detail in Section 12 - Risk Matrix Tables.

### 8. Defects Identified during Safety Inspections

These are a list of examples of the types of defects to be considered during a safety Inspection. They are examples and cannot cover all hazards likely to be observed. See **Note 1** after this table.

Footway	<ul> <li>Potholes</li> <li>Trips</li> <li>Areas of Depression</li> <li>Damaged Bollards</li> <li>Missing/Rocking Poor Surface Condition</li> <li>Gaps in Condition</li> <li>Ironwork missing broken, too high/low</li> </ul>					
Kerbing	<ul> <li>Poor Condition</li> <li>Missing</li> <li>Dislodged</li> <li>Loose/Rocking</li> <li>Uneven</li> </ul>					
Carriageway	<ul> <li>Pothole</li> <li>Flooding</li> <li>Areas of</li> <li>Depression</li> <li>Delamination</li> <li>Rutting</li> <li>Gaps/Cracks</li> <li>Edge Damage</li> <li>Debris</li> <li>Debris</li> <li>Ironwork missing broken, too high/low</li> </ul>					
Verges	• Rutting • Obstructions • Damage					
Overall	<ul> <li>Overhanging Vegetation</li> <li>Obstructions</li> <li>Damaged or non-operational traffic lights</li> <li>Damaged or missing road signs/name plates</li> <li>Damaged litter bins</li> <li>Streetlights, bollards, electrical street furniture, missing covers/day burners</li> <li>Guard railing/VRS/Parapets</li> <li>Damaged structures e.g., retaining walls /bus shelters</li> <li>Trees exhibiting potential risk to highways users</li> </ul>					
Lining	<ul><li>Safety related</li><li>Give way lines</li><li>Stop lines</li></ul>					
Signs/SNPs	Safety related					

**Note:** Please note that this table is not an exhaustive list, but covers typical items inspected in a safety inspection on the highway. It is a requirement of a competent highways inspector to identify all potential hazards and make either a judgement or seek additional assistance in the event they encounter a potential hazard that is outside of their expertise. Hazards that are not a highway responsibility will be passed to the appropriate department or organisation

although if there is an immediate risk and the 3<sup>rd</sup> party cannot attend it is the duty of the Highways Service to temporarily make safe the area and if appropriate recharge any costs – The primary concern is to safeguard highway users, and this must be the priority for the highway inspector.

Defect types that are available to the highways inspectors to select on AMX on site are as per table 1 - pages 22 & 23. Where it is felt a defect code does not match the defect presented then the closest defect type should be used, and the issue reported back to line manager for further guidance.

#### a. Snow/Floodwater Covering Highway Inspection Area

During periods of snowfall or highway flooding, to the extent that the highway surface is covered rendering it unviable to safely inspect the highway and identify defects, the highways inspectors are to make the judgement, record and document the decision on AMX system and notify the Highways Service Manager immediately in writing.

The MKCC Highways Service Manager will be responsible for submission of a recovery plan to the Contract Service Manager for approval in line with the annual inspection programme (section 2 – roles & responsibilities), with an associated method statement within 24 hours of making the aforementioned decision. The recovery plan, dependent upon duration and location of lying snow/floodwater, should be a risk-based approach, targeted to the completion of highway inspections on those highways with a high and medium route risk.

## b. Approach to Areas of High-Density Levels of Carriageway Potholes and Surface Materials – Proximity Repairs

Where there are areas identified with a high density of carriageway potholes at or below investigatory levels, it may not be cost effective or asset efficient to only repair those that are considered safety defects. Therefore, when an actionable pothole is identified in an inspection, if additional defects are also identified within 10 m2 of said pothole that fall into the 'planned works' green category – Table 2 – Defect Categorisation Page 26, they shall also be repaired. Where the inspector judges that the surface condition over a larger area shows evidence of significant deterioration it may be more cost effective to repair only the safety critical defects and seek Highways Service Manager guidance on the most appropriate treatment for the larger area concerned and classified/raised as an 84-day priority repair – table 2 – defect categorisation.

#### c. Works outside the Scope of the Defect Matrix

Works identified that are outside the scope of the defect matrix are to be discussed with the Highways Service Manager and included in a planned works programme if budgets allow.

### d. Hazards Responsibility of other Council Services

Any hazards identified that are the responsibility of associated council services shall be recorded and emailed to MKCC Customer Contact Centre (CCS) for re-allocation to the relevant department e.g., trees, bus shelters, broken glass, streetlights out etc. Where these result from a customer enquiry, the enquiry can be automatically rerouted to the responsible department via AMX.

Highway inspectors are undertaking regular surveillance of the highway network as part of their safety inspections and will report any obvious defects on structures that require urgent attention to the structures team; or if immediate action is needed (i.e., out of hours), they shall arrange for traffic management to isolate the structure and then inform the structures team.

### **Table 1 - Defect Codes on AMX**

Defects are raised in AMX using a Schedule of Activities as detailed below. The Schedule items are mirrored in the Contractor's system to allow reporting on quantities and costs.

Code	Description
240031100	COR-003 Drainage Maintenance REVENUE
240031101	DCWG - Carriageway Gully
240031102	DAHG -Ad hoc Gully Attendance
240031103	DCKW - Carriageway Kerb Weirs
240031104	DFG - Footway / Redway Gully
240031105	DCMK -CMK Underpass Footway Gully
240031106	DRP - Drainage Pipes
240031107	DRM - Manholes
240031108	DRCP - Catch pits
240031109	DRHW - Headwalls
240031110	DRCUL - Culverts <900mm
240031111	DRTS - Trash Screens
240031112	DRSUB - Electric Subway Pumps
240031113	DRSK - Soakaways
240031114	DRDIT - Ditches
240031115	DRFD - Filter Drains
240031116	DRGR - Grips
240031117	DRKD - Linear Kerb Drainage
240031118	DRLD - Linear Drainage e.g. ACO
240031119	DRCH - Channelised Concrete Ditches
240031120	DRBP - Wet / Dry Balancing Ponds
240042000	COR-004 Road Markings REVENUE
240051801	Basic Facility
240051802	WSRT - Route Treatment
240051803	WSSBR - Additional Salt Bin Refill
240051804	WSISB - Provide & install salt bin
240051805	WSDSB - Remove & dispose salt bin
240051806	WSHS - Hand salting
240060700	COR-006 Structures Routine & General Maint.REVENUE
240071400	COR-007 Street Lighting REVENUE
240071401	SLC - Lighting Columns
240071402	SLU - Underpass/Structures Lighting
240071403	SLL - Lanterns
240071404	SLET - Electrical Testing
240071406	SLFP - Feeder pillars
240071407	SLCMS - Nodes/Base Stations
240071409	SIB - Illuminated bollards
240071410	SIS - Illuminated Signs
240071411	SNB - Non illuminated bollards
240071412	SLDNO - DNO Transfers
240071413	SLFL - Floodlights
240071414	SLCCTV - Mobile CCTV Cameras

240071415	SLEMERG - Street Lighting Emergency
240082300	COR-008 Traffic Signals REVENUE
240082305	TSBB - Belisha Beacons
240082306	TSVMS - Static Variable Messaging Signs
240082307	TSCL - Traffic Counter Loops
240082308	TSVAS - Vehicled Actuated Signs
240082309	TSWW - School crossing flashing signs (wigwags)
240090100	COR-009 Highway Emergency Response REVENUE
240090200	COR-009 Highway Routine & Reactive Maint. REVENUE
240090204	HWSF - Street Furniture
242500001	Carriageway Surface Treatment Improvements
242500002	Bridges & Highway Structures Schemes
242500003	Drainage Improvement Schemes
242500004	Street Lighting Improvements
242500005	Traffic Signs & Street Name Plates
242500006	Traffic Management Schemes
242500007	Traffic Signal Improvements
242500008	Road Safety Schemes
242500009	Vehicle Safety Fencing Upgrades
242500010	Major Projects
242500011	Carriageway Construction / Improvements
242500012	Early Contractor Involvement
242500013	Carpark Maintenance & Improvements
242500014	Accessibility Improvements
242500015	Footway Redway Construction / Improvements
242500016	Developer Projects
242500017	Other Projects (Parish Landscape External Bodies)
240042001A	RMWL: Linear White Lining
240042001B	RMYL: Linear Yellow Lining
240042001C	RMS: Shape
240042001D	RMA: Arrow
240042001E	RM<5: Words less than 5 letters
240042001F	RM>5: Words more than 5 letters
240060701A	HSCVCS - Clear Vegetation from Concrete Structures
240060701AA	HSRAC - Repair Anti-slip Coating
240060701B	HSCVMS - Clear Vegetation from Masonry Structures
240060701BB	HSBR - Bagwork Repair
240060701C	HSCVTF - Clear Vegetation from Timber Footbridges
240060701CC	HSTNBS - Parapet Nuts and Bolts Specialist
240060701D	HSCKS - Cut and Kill Sapling
240060701DD	HSPM - Parapet Mesh repair Specialist
240060701E	HSCTB - Cut tree branch
240060701EE	HSTNB - Tighten Nuts and Bolts General
240060701G	HSDCD - Drainage Cleansing Deck
240060701H	HSDCWP - Drainage Cleansing Weep pipes
240060701J	HSCBS - Cleaning Bearing Shelves
240060701K	HSBCG - Bearing Cleaning and Greasing
240000701K	Tibbed bearing cleaning and dreasing

240060701M HSWB - Watercourse Blockages  240060701P HSMMR - Minor Repointing  240060701P HSMMR - Minor Masonry Repair  240060701B HSMGR - Minor Concrete Repair  240060701B HSMGR - Minor Tubular Guardrail repair  240060701L HSMMT - Minor Painting Timber  240060701L HSMPT - Minor Painting Timber  240060701L HSMPS - Minor Painting Steel  240060701L HSMPS - Minor Painting Steel  240060701W HSRDP - Replace Timber Deck Plank  240060701W HSRGDP - Replace GRP Deck Plank  240060701Y HSTPI - Replace Timber Parapet Infill  240060701Y HSTPI - Replace GRP Parapet Infill  240060701Z HSRGGS - Replace GRP Orip Strip  240060701Z HSRMPC - Routine Maintenance Porte Cochere  240071405A SLCG - Control gear  240071405A SLCG - Cut-Out/Isolator  240071408B SLCO - Cut-Out/Isolator  240071408B SLCO - Cut-Out/Isolator  240071408B SLCO - SLCO - Cut-Out/Isolator  240082301A TSGL: Green Lamp/Lens Out  240082301B TSAL: Amber Lamp/Lens Out  240082301D TSCN: Controller Faulty/Damaged  240082301D TSCN: Controller Faulty/Damaged  240082301T TSP: Power Failure  240082301F TSGML: Green Man Out  240082301F TSGML: Green Man Out  240082301F TSSI: Red Lamp/Lens Stuck On  240082301T TSSI: Red/Green Lamp/Lens Stuck On  240082301T TSSI: Red/Green Lamp/Lens Stuck On  240082301T TSSI: Red/Green Lamp/Lens Stuck On  240082301T TSSIC Sci Lights Constantly Changing  240082301T TSSIC Signal Sequence Check Required  240082301T TSPF: Detector Fault Push Button  240082301T TSPF: Detector Fault Push Button  240082301T TSPF: Detector Fault Push Eault  240082301T TSPF: Signal Head Damaged  24009201A HWR: Highway Ironworks  24009001B HWR: Highway Firutures Emergency  24009001B HWR: Highway Ironworks  24009001B HWR: Highway Ironworks  24009001B HWR: Highway Ironworks  24009001C CWCE: Cway Comp. Event  240090001E HWMP: Highway Mastic Ironwork Patch  240090002CE FWCE: Fway Comp. Event		
240060701P HSMMR - Minor Masonry Repair 240060701R HSMCR - Minor Concrete Repair 240060701S HSTGR - Minor Tubular Guardrail repair 240060701S HSMRTG - Mesh Repair Tubular Guardrail 240060701T HSMPT - Minor Painting Timber 240060701U HSMPS - Minor Painting Steel 240060701W HSRTDP - Replace Timber Deck Plank 240060701W HSRTDP - Replace GRP Deck Plank 240060701W HSRTDP - Replace GRP Parapet Infill 240060701X HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405A SLCG - Cut-Out/Isolator 240071408B SLPC - Highway private cable 240071408B SLPC - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301F TSGML: Green Lamp/Lens Out 240082301F TSSFL: Red Jamp/Lens Out 240082301F TSSFL: Red Jamp/Lens Out 240082301F TSSFL: Walt Lamp Out 240082301F TSSFL: Walt Lamp Out 240082301F TSSFL: Walt Lamp Out 240082301F TSSFL: Sed/Green Lamp/Lens Out 240082301F TSSFL: Walt Lamp Out 240082301F TSSFP: Detector Fault Unspecified 240082301N TSLG: Lights Constantly Changing 240082301D TSSF: Signal Pole Damaged 240082301D TSUTC: UTC Failure 240082301D TSUTC: UTC Failure 24009201A HWRE: Highway Ironworks 240090201E HWMP: Highway Ironworks 240090201E HWMP: Highway Ironworks 240090201E HWMP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Ironwork Patch	240060701M	HSWB - Watercourse Blockages
240060701Q HSMCR - Minor Concrete Repair 240060701R HSTGR - Minor Tubular Guardrail repair 240060701T HSMPT - Minor Painting Timber 240060701T HSMPT - Minor Painting Timber 240060701T HSMPS - Minor Painting Timber 240060701W HSRGDP - Replace Timber Deck Plank 240060701W HSRGDP - Replace GRP Deck Plank 240060701X HSTDP - Replace GRP Deck Plank 240060701X HSTPI - Replace Timber Parapet Infill 240060701Z HSRGGS - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Parapet Infill 240060701Z HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405A SLCG - Cout-Out/Isolator 240071405A SLCG - Cout-Out/Isolator 240071405A SLCG - Cout-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLP - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301T TSCN: Controller Faulty/Damaged 240082301T TSCN: Controller Faulty/Damaged 240082301T TSSML: Multiple Lamp/Lens Out 240082301T TSSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSDFPB: Detector Fault Unspecified 240082301M TSDFU: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301D TSSPF: Signal Head Damaged 240082301T TSPF: Signal Head Damaged 240082301T TSPF: Signal Pole Damaged 240082301T TSPF: Signal Pole Damaged 240082301T TSPS: Signal Sequence Check Required 240082301T TSPS: Signal Sequence Check Required 240082301T TSPF: Signal Head Damaged 240082301T TSPF: Signal Head Damaged 240082301T TSPS: Signal Pole Damaged 240082301T TSPS: Signal Pole Damaged 240082301T TSPF: Signal Head Damaged 240082301T TSPS: Signal Sequence Check Required 240082301T TSPS: Signal Pole Damaged 24009201D HWEMERG: Hway Emergency 24009001DF HSEMERG - Highway Isro	240060701N	HSMR - Minor Repointing
240060701R HSTGR - Minor Tubular Guardrail repair 240060701T HSMPT - Minor Painting Timber 240060701U HSMPS - Minor Painting Steel 240060701W HSRTDP - Replace Timber Deck Plank 240060701W HSRDP - Replace Timber Deck Plank 240060701W HSRDP - Replace GRP Deck Plank 240060701W HSTPI - Replace Timber Parapet Infill 240060701Y HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301T TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301F TSSEML: Multiple Lamp/Lens Stuck On 240082301T TSSL: Red/Green Lamp/Lens Stuck On 240082301T TSDFD: Detector Fault Unspecified 240082301M TSDFU: Detector Fault Unspecified 240082301M TSDFU: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301D TSDF: Signal Pole Damaged 240082301T TSP: Signal Pole Damaged 240082301D TSCS: Signal Sequence Check Required 240082301D TSCS: Signal Sequence Check Required 240082301D TSCS: Signal Sequence Check Required 240082301D TSUTC: UTC Failure 240090201A HWEMERG: Hway Emergency 240090201B HWIR: Highway Ironworks 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201B HWMP: Highway Mastic Ironwork Patch 240090202B FWW: Fway Bla	240060701P	HSMMR - Minor Masonry Repair
240060701S HSMRTG - Mesh Repair Tubular Guardrail 240060701T HSMPT - Minor Painting Timber 240060701W HSMPS - Minor Painting Steel 240060701W HSRTDP - Replace Timber Deck Plank 240060701W HSRGDP - Replace GRP Deck Plank 240060701W HSRGDP - Replace GRP Deck Plank 240060701W HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060701Z HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405A SLCG - Control gear 240071405A SLCC - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLP1 - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301F TSGML: Green Lamp/Lens Out 240082301F TSGML: Green Lamp/Lens Out 240082301G TSWL: Wait Lamp Out 240082301T TSDFPB: Detector Fault Push Button 240082301M TSDFD: Detector Fault Push Button 240082301M TSDFD: Detector Fault Unspecified 240082301N TSDFD: Detector Fault Unspecified 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301D TSDFC: UTC Failure 240090201A HW EMERG: Hway Emergency 240090201B HWIR: Highway Isroworks 240090201B CWW: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Mastic Ironwork Patch 240090201B HWMP: Highway Mastic Ironwork Patch	240060701Q	HSMCR - Minor Concrete Repair
240060701T         HSMPT - Minor Painting Timber           240060701U         HSMPS - Minor Painting Steel           240060701W         HSRTDP - Replace Timber Deck Plank           240060701W         HSRGDP - Replace GRP Deck Plank           240060701W         HSTPI - Replace GRP Deck Plank           240060701C         HSRGS - Replace GRP Parapet Infill           240060701Z         HSRGGS - Replace GRP Parapet Infill           240060702F         HSRMPC - Routine Maintenance Porte Cochere           240071405A         SLCO - Cut-Out/Isolator           240071405B         SLCO - Cut-Out/Isolator           240071408A         SLPJ - Highway private cable           240071408B         SLPJ - Highway private cable Joint           240082301B         TSGL: Green Lamp/Lens Out           240082301B         TSAL: Amber Lamp/Lens Out           240082301D         TSCN: Controller Faulty/Damaged           240082301T         TSCN: Controller Faulty/Damaged           240082301T         TSGML: Green Man Out           240082301T         TSSMI: Multiple Lamp/Lens Out           240082301T         TSSMI: Red/Green Lamp/Lens Stuck On           240082301T         TSDFDB: Detector Fault Push Button           240082301T         TSDFDB: Detector Fault Push Button           240082301T	240060701R	HSTGR - Minor Tubular Guardrail repair
240060701U HSMPS - Minor Painting Steel 240060701W HSRTDP - Replace Timber Deck Plank 240060701W HSRGDP - Replace GRP Deck Plank 240060701X HSTPI - Replace GRP Deck Plank 240060701X HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240071405A SLCG - Control gear 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408B SLPJ - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301A TSGL: Green Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301T TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301F TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301M TSDFU: Detector Fault Unspecified 240082301M TSPF: Pedestrian Phase Fault 240082301D TSPF: Pedestrian Phase Fault 240082301D TSPF: Signal Pole Damaged 240082301D TSSC: Signal Sequence Check Required 240082301D TSSC: Signal Sequence Check Required 240082301D TSCC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201C HWKK: Highway Mastic Ironwork Patch 240090201A FWB: Fway Black < 1m² 240090201B HWMIP: Highway Mastic Ironwork Patch 240090201B FWW: Fway White < 1m²	240060701S	HSMRTG - Mesh Repair Tubular Guardrail
240060701V HSRTDP - Replace Timber Deck Plank 240060701W HSRGDP - Replace GRP Deck Plank 240060701X HSTPI - Replace GRP Deck Plank 240060701Y HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408B SLPJ - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301T TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301F TSSL: Red/Green Lamp/Lens Out 240082301F TSSL: Red/Green Lamp/Lens Out 240082301F TSWL: Wait Lamp Out 240082301N TSUC: Wait Lamp Out 240082301N TSUC: Ushts Constantly Changing 240082301N TSLCG: Lights Constantly Changing 240082301N TSLCG: Lights Constantly Changing 240082301N TSH: Signal Head Damaged 240082301T TSPF: Pedestrian Phase Fault 240082301T TSPF: Signal Pole Damaged 240082301T TSPF: Signal Pole Damaged 240082301T TSPC: Signal Sequence Check Required 240082301T TSUC: UTC Failure 24009201A HW EMERG: Highway Structures Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway White < Im² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201C HWCK: Highway Mastic Ironwork Patch 240090201C HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240060701T	HSMPT - Minor Painting Timber
240060701W HSRGDP - Replace GRP Deck Plank 240060701X HSTPI - Replace Timber Parapet Infill 240060701Y HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405B SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301T TSFP: Power Failure 240082301F TSGML: Green Man Out 240082301F TSGML: Green Lamp/Lens Out 240082301F TSGML: Green Lamp/Lens Out 240082301T TSSH: Red/Green Lamp/Lens Out 240082301T TSSH: Red/Green Lamp/Lens Out 240082301T TSWI: Wait Lamp Out 240082301N TSUC: Gights Constantly Changing 240082301N TSLCG: Lights Constantly Changing 240082301N TSLCG: Lights Constantly Changing 240082301D TSPF: Pedestrian Phase Fault 240082301T TSPF: Signal Pole Damaged 240082301D TSSC: Signal Sequence Check Required 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301T TSP: Signal Pole Damaged 240082301D TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < Im² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201C HWCK: Highway Mastic Ironwork Patch 240090201C HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240060701U	HSMPS - Minor Painting Steel
240060701X HSTPI - Replace Timber Parapet Infill 240060701Y HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408A SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301D TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301F TSGML: Wait Lamp Out 240082301F TSDFP: Power Failure 240082301F TSDFP: Pedestrian Pout 240082301F TSDFPB: Detector Fault Push Button 240082301F TSDFU: Detector Fault Push Button 240082301F TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301T TSPF: Pedestrian Phase Fault 240082301T TSPF: Signal Head Damaged 240082301T TSPS: Signal Sequence Check Required 240082301T TSPS: Signal Sequence Check Required 240082301D TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101B HWIR: Highway Ironworks 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201B HWIR: Highway Ironwork Patch 240090201B HWMIP: Highway Mastic Ironwork Patch 240090201B FWW: Fway White < 1m² 240090201B FWW: Fway White < 1m²	240060701V	HSRTDP - Replace Timber Deck Plank
240060701Y HSTPI - Replace GRP Parapet Infill 240060701Z HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408A SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301D TSCN: Controller Faulty/Damaged 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301K TSDFPB: Detector Fault Push Button 240082301N TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSPF: Signal Head Damaged 240082301T TSPS: Signal Sequence Check Required 240082301D TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101B HSEMERG - Highway Structures Emergency 240090201B CWW: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201B HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240060701W	HSRGDP - Replace GRP Deck Plank
2400607012 HSRGGS - Replace GRP Grip Strip 240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Stuck On 240082301G TSML: Multiple Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301L TSDFPB: Detector Fault Push Button 240082301L TSDFPB: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSPF: Signal Head Damaged 240082301T TSPF: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWMR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C HWCK: Highway Mastic Ironwork Patch 240090201B HWMP: Highway Mastic Ironwork Patch 240090201B FWW: Fway White < 1m² 240090201B HWMP: Highway Mastic Ironwork Patch 240090201B FWW: Fway Black < 1m² 240090201B FWW: Fway Black < 1m²	240060701X	HSTPI - Replace Timber Parapet Infill
240060702F HSRMPC - Routine Maintenance Porte Cochere 240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301E TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301L TSDFPB: Detector Fault Push Button 240082301L TSDFPB: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301C TSPPF: Pedestrian Phase Fault 240082301T TSPF: Signal Head Damaged 240082301T TSPF: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101A HW EMERG: Highway Structures Emergency 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201A HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202A FWB: Fway Black < 1m² 240090202A FWB: Fway Black < 1m²	240060701Y	HSTPI - Replace GRP Parapet Infill
240071405A SLCG - Control gear 240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301F TSGML: Multiple Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301N TSDFU: Detector Fault Unspecified 240082301N TSDFU: Detector Fault Unspecified 240082301N TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSPF: Signal Head Damaged 240082301T TSPC: Signal Pole Damaged 240082301T TSSC: Signal Sequence Check Required 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201E HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240060701Z	HSRGGS - Replace GRP Grip Strip
240071405B SLCO - Cut-Out/Isolator 240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301K TSWL: Wait Lamp Out 240082301M TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C HWCK: Highway Mastic Ironwork Patch 240090201B HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240060702F	HSRMPC - Routine Maintenance Porte Cochere
240071408A SLPC - Highway private cable 240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301F TSGML: Green Man Out 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101A HW EMERG: Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201C CWCE: Cway Comp. Event 240090201E HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090201B HWMP: Highway Mastic Ironwork Patch 240090201B HWMP: Highway Mastic Ironwork Patch 240090202B FWW: Fway White < 1m² 240090202B FWW: Fway Black < 1m²	240071405A	SLCG - Control gear
240071408B SLPJ - Highway private cable Joint 240082301A TSGL: Green Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301F TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301F TSGML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301L TSDFPB: Detector Fault Push Button 240082301L TSDFPB: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201C EWCE: Cway Comp. Event 240090201B HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202A FWB: Fway Black < 1m² 240090201B HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090201B FWW: Fway White < 1m²	240071405B	SLCO - Cut-Out/Isolator
240082301A         TSGL: Green Lamp/Lens Out           240082301B         TSAL: Amber Lamp/Lens Out           240082301C         TSRL: Red Lamp/Lens Out           240082301E         TSPF: Power Failure           240082301F         TSGML: Green Man Out           240082301G         TSML: Multiple Lamp/Lens Out           240082301H         TSSL: Red/Green Lamp/Lens Stuck On           240082301K         TSWL: Wait Lamp Out           240082301L         TSDFPB: Detector Fault Push Button           240082301M         TSDFU: Detector Fault Unspecified           240082301N         TSLCG: Lights Constantly Changing           240082301P         TSMF: Miscellaneous Fault (Unknown)           240082301Q         TSPPF: Pedestrian Phase Fault           240082301R         TSH: Signal Head Damaged           240082301T         TSP: Signal Pole Damaged           240082301U         TSSC: Signal Sequence Check Required           240082301U         TSSC: Signal Sequence Check Required           240082310J         TSUTC: UTC Failure           24009201A         HW EMERG: Hway Emergency           240090201B         CWB: Cway White < 1m²	240071408A	SLPC - Highway private cable
240082301B TSAL: Amber Lamp/Lens Out 240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFPB: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301N TSLGS: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPFF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201B HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240071408B	SLPJ - Highway private cable Joint
240082301C TSRL: Red Lamp/Lens Out 240082301D TSCN: Controller Faulty/Damaged 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301M TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201A HWMP: Highway Mastic Ironwork Patch 240090201A HWMP: Highway Mastic Patch 240090201A FWB: Fway Black < 1m² 240090201B HWMP: Highway Mastic Patch 240090201A FWB: Fway Black < 1m² 240090201B HWMP: Highway Mastic Patch	240082301A	TSGL: Green Lamp/Lens Out
240082301D TSCN: Controller Faulty/Damaged 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201A FWB: Fway Black < 1m² 240090201A HWMP: Highway Mastic Patch 240090201B HWMP: Highway Mastic Patch 240090201B FWW: Fway White < 1m² 240090201B HWMP: Highway Mastic Patch 240090201B FWW: Fway White < 1m²	240082301B	TSAL: Amber Lamp/Lens Out
240082301D TSCN: Controller Faulty/Damaged 240082301E TSPF: Power Failure 240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201A FWB: Fway Black < 1m² 240090201A HWMP: Highway Mastic Patch 240090201B HWMP: Highway Mastic Patch 240090201B FWW: Fway White < 1m² 240090201B HWMP: Highway Mastic Patch 240090201B FWW: Fway White < 1m²	240082301C	TSRL: Red Lamp/Lens Out
240082301F TSGML: Green Man Out 240082301G TSML: Multiple Lamp/Lens Out 240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301T TSP: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201C HWCK: Highway Mastic Ironwork Patch 240090201E HWMIP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301D	TSCN: Controller Faulty/Damaged
240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301Q TSPF: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201C HWCK: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201E HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301E	TSPF: Power Failure
240082301H TSSL: Red/Green Lamp/Lens Stuck On 240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082301U TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201E HWMP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301F	TSGML: Green Man Out
240082301K TSWL: Wait Lamp Out 240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101F HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301G	TSML: Multiple Lamp/Lens Out
240082301L TSDFPB: Detector Fault Push Button 240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301H	TSSL: Red/Green Lamp/Lens Stuck On
240082301M TSDFU: Detector Fault Unspecified 240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301K	TSWL: Wait Lamp Out
240082301N TSLCG: Lights Constantly Changing 240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202B FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301L	TSDFPB: Detector Fault Push Button
240082301P TSMF: Miscellaneous Fault (Unknown) 240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301M	TSDFU: Detector Fault Unspecified
240082301Q TSPPF: Pedestrian Phase Fault 240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301N	TSLCG: Lights Constantly Changing
240082301R TSH: Signal Head Damaged 240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301P	TSMF: Miscellaneous Fault (Unknown)
240082301T TSP: Signal Pole Damaged 240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301Q	TSPPF: Pedestrian Phase Fault
240082301U TSSC: Signal Sequence Check Required 240082310J TSUTC: UTC Failure 240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301R	TSH: Signal Head Damaged
240082310J       TSUTC: UTC Failure         240090101A       HW EMERG: Hway Emergency         240090101FF       HSEMERG - Highway Structures Emergency         240090201A       CWB: Cway Black < 1m²	240082301T	TSP: Signal Pole Damaged
240090101A HW EMERG: Hway Emergency 240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201C CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082301U	TSSC: Signal Sequence Check Required
240090101FF HSEMERG - Highway Structures Emergency 240090201A CWB: Cway Black < 1m² 240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240082310J	TSUTC: UTC Failure
240090201A       CWB: Cway Black < 1m²	240090101A	HW EMERG: Hway Emergency
240090201B CWW: Cway White < 1m² 240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m² 240090202B FWW: Fway White < 1m²	240090101FF	HSEMERG - Highway Structures Emergency
240090201B HWIR: Highway Ironworks 240090201C HWCK: Highway Kerbs Edgings 240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201A	CWB: Cway Black < 1m <sup>2</sup>
240090201C HWCK: Highway Kerbs Edgings 240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201B	CWW: Cway White < 1m²
240090201CE CWCE: Cway Comp. Event 240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201B	HWIR: Highway Ironworks
240090201D HWMIP: Highway Mastic Ironwork Patch 240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201C	HWCK: Highway Kerbs Edgings
240090201E HWMP: Highway Mastic Patch 240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201CE	CWCE: Cway Comp. Event
240090202A FWB: Fway Black < 1m <sup>2</sup> 240090202B FWW: Fway White < 1m <sup>2</sup>	240090201D	HWMIP: Highway Mastic Ironwork Patch
240090202B FWW: Fway White < 1m <sup>2</sup>	240090201E	HWMP: Highway Mastic Patch
	240090202A	FWB: Fway Black < 1m <sup>2</sup>
240090202CE FWCE: Fway Comp. Event	240090202B	FWW: Fway White < 1m <sup>2</sup>
	240090202CE	FWCE: Fway Comp. Event

240090203A	RWB: Rway Black < 1m <sup>2</sup>
240090203B	RWW: Rway White < 1m <sup>2</sup>
240090203CE	RWCE: Rway Comp. Event
242500999	Third Party Green Claims

### 9. Information to be Added to the Defect

To enable the repair teams to undertake effective repairs on the first visit, it is imperative that certain key information is passed on to the Contractor. It should be recorded in clear and concise fashion to aid accurate location, to determine traffic management requirements and correct materials to repair the defect effectively.

This information must be recorded during the inspection on site, and it is vital therefore, that the information is recorded accurately. The guidance within this code will assist in the process.

Critical pieces of information are required. These are:

- a. Location
- b. Type of defect and extent of repair
- c. Category of defect
- d. Materials required for the repair
- e. Any other site-specific details
- f. Photograph of defect

#### a. Location

Defects are logged electronically and as such have associated coordinates that are provided to the Contractor's tablets. Photographs are also taken of the defects. However, where appropriate, defects shall be marked with temporary road marking paint as this will help the repair team to quickly locate a defect.

To locate a defect efficiently, the repair teams require four pieces of information:

- Street name
- The position of the defect within the street
- The position of the defect on the highway, e.g., by kerb, near centre line, to side of gully
- · Type of defect

Location information should use a combination of the following:

- House number
- Streetlamp column number
- Building name
- Road junction
- Clear un-moveable landmark

What if there are no houses in the street? Where no houses exist, use streetlamp column numbers. What if there are no houses and no lamp columns? Where neither houses nor lamp columns exist, mark the defects with road marking paint and number where necessary. Use other information as much as possible, e.g., junction of road, distance from a landmark object, telegraph pole ref. no.

#### Using building names

Building names are often more difficult to locate especially on long roads, so if it is necessary to give a building name it would help the repair team to have some additional information such as 'Fairhaven between L/Col 21 and L/Col 23'.

#### **Examples**

- Outside 17
- Adjacent to 21
- Junction with ....
- 5 metres from L/Col 16

Position information should use a combination of the following:

- Channel of carriageway
- At rear of footway
- Adjacent to
- Edge of kerb
- At radius
- On verge
- Central reservation
- · On vehicle crossing

This list is by no means definitive. However, by using combinations of these and other similar terms it is possible to give simple but clear instructions on a works order to assist the repair team to quickly locate the defect.

#### **Examples**

- Outside 21, pothole in channel of carriageway
- Property Mansion House, between L/Col 15 and L/Col 17 sunken slabs to kerb edge
- Opposite junction with Milton Drive, sunken kerb

### b. Type of Defect and Extent of Repair

After selecting the appropriate defect type code from AMX, it is advisable to detail in the description any further information regarding the type of defect, in addition to the materials that you will list, for example: 240090201B HWIR: Highway Ironworks is the selected schedule of activity (SoA), then add to the description what type and size of ironworks it is that is missing.

In many instances the team will be unable for practical reasons to repair the precise area of defective highway. It may be necessary for instance, to cut back on a defective area of bituminous surface beyond the defect itself to remove loose surfacing which is not visible to

the eye. The equipment necessary to undertake a repair may also require a minimum space to carry out its role effectively.

As a general rule, for the permanent repair to potholes; areas should be recorded at a minimum 300mm x 300mm and an allowance for cut back of 100 mm on all sides should be made to create a square edged repair. All carriageway patches in bituminous shall be over banded (minimum SRV 55).



For repairs to flagged and bituminous surfacing the measures should be as accurate as possible as they give a good indication as to the materials required and will diminish the need for variation payments when the works order is completed.

### c. Traffic Management

A full TM assessment will be undertaken at planning/scheduling stage by the contractor. All TM costs are included in the identified annual lump sum (see Contract Scope).

#### d. Materials

Where it is apparent that materials are necessary to carry out a repair, the materials should be stated e.g., take up and relay two sq. metres of uneven paving, replace 1 no 600 x 600 x 50mm silver grey slab.

When describing defects, it will be necessary to refer to the particular materials which are affected by the defect. In some cases, the defect may affect several materials, and these will also need to be covered within the description.

e.g., Outside 27 - depression in bitmac footway 0.3 sq. m, 2 sunken pcc kerbs, also 2 sq. m, of rocking pcc slabs and 1 no  $150 \times 150 \times 15$ 

Such information is particularly helpful to the teams and reduces unproductive time. Where it is necessary to replace an item, if possible, the product type and/or size should be given.

e.g.: 5 x 10 (125 x 255) PCC bull nose kerb

Road gully cover 255 x 300 x 100mm PCC footway dished channel 150 wide

PCC slab 600 x 600 x 50mm, note any finish/colour/type

Where there are items of defective street furniture it is important that the particular type of street furniture is noted. Photographs should always be taken to aid identification.

### e. Other Site-Specific Details

Any further details that may help service delivery should be included, in the descriptions. This includes proximity to schools, requirement for coning an area off the night prior to ensure full access to site, and any other such local information that could be useful to the contractor.

### 10. Defects not under the ownership of the Council

During an inspection, defects may be identified which are not the responsibility of the Council to repair. The Council does however have a duty of care to the users of the highway. The staff involved in this activity shall therefore take steps to ensure that the party responsible for the repair are made aware of the defect and if necessary, take interim action to make a defect temporarily safe if appropriate/possible.

### a. Statutory Undertakers

#### **Defective apparatus**

Where Highways Inspectors come across defective utility apparatus, they will access Digdat and other online utility asset information to ensure the defect is utility owned, and then contact the relevant team stating what type of cover/defective apparatus it is e.g., foul, or clean water. The team will issue a Section 81 notice to the utility company with the correct information in line with the procedures agreed by the New Roads and Streetworks Act (NRSWA) section.

#### **Defective reinstatements**

Where a Highways Inspector identifies a defective reinstatement suspected of belonging to a Statutory Undertaker this is recorded, stating where possible the undertaker concerned. This information is passed on to the NRSWA team who review whether it is still within the guarantee and if appropriate will serve the undertaker with a defect notice requiring them to take remedial action. Photographs should also be sent to assist the NRSWA team. If it is not within the guarantee period, then the defect will be passed back to the contractor to action.

Any emergency defects in reinstatements will be dealt with in accordance with this Code of Practice irrespective of the ownership to ensure the ultimate safety to the travelling public.

#### b. Unknown parties

Any emergency defect, where the owner is unknown, shall be recorded and action taken to make the defect safe. Investigations shall then be undertaken by the Inspector/MKCC to locate the responsible party.

Note: Hazards that are not a highway responsibility will be passed to the appropriate department or organisation, although if there is an immediate risk and the 3<sup>rd</sup> party cannot attend it is the duty of the Highways Service to temporarily make safe the area and if appropriate recharge any costs. The primary concern is to safeguard highway users and this must be the priority for the Highway Inspector.

### 11. Defect Categorisation – Table 2

Priority	Timescale for Defect Repair
No stand-alone defects. Undertaken as proximity carriageway pothole repairs works if location contains adjacent actionable repairs.	Defects under investigatory level – No action if visual risk assessment eliminates need for repair.  Note: Carriageway Potholes identified that are under investigatory levels but are located within 10m2 of investigatory level defects will be repaired at the same time as other higher priority pothole repairs (proximity pothole repairs – see section 8b).
84-day Works (84 days shall be defined as 84 calendar days)	Carriageway, footway, and all other categories:  A defect that, in the judgment of the inspector following visual risk assessment, should be included in the 84-day works programme— see section 8.b
See Note 1	<b>Note 1</b> : Defects in the yellow category shall be designated as 84-day priority— see process in Section 13. For example a large area of carriageway/footway may show an overall deterioration in condition with localised safety defects that can be temp filled under higher priority (only actionable defects), the larger area is then prioritised as a 84 day permanent programmed job if it will deteriorate and further actionable defects will appear.
28-day Works (28 days shall be defined as 28 calendar days)	Carriageway, footway, and all other categories:  A defect that, in the judgment of the inspector following visual risk assessment, should be included in the 28-day planned works programme,
See Note 2	<b>Note 2:</b> Defects in the amber category shall be designated as 28-day priority— see process in Section 13, however the inspector will have the discretion to increase/decrease the defect as a

	greater/lesser hazard to users of the highways. For example, an access frequented by vulnerable users would attract a higher priority whereas a defect at the end of an alleyway with no pedestrian through traffic would be considered a lower priority and categorised accordingly. Any discretion used to change a defect priority as described above MUST include a note on AMX from the inspector, giving reasons for the decision to either increase or decrease the priority.		
Cat-1 (24 hours) or 1A (2 hours)	Carriageway and footway and all other categories:  A defect that, in the judgment of the inspector following visual risk assessment, should be repaired or made safe within 2 hours (CAT 1A) or 24 hours (CAT 1). All defects that are only made safe are to be repaired permanently by inclusion in the 28/84 day planned works programme unless otherwise directed by the Service Manager.		

**Table 3 - Visual Risk Assessment Matrix (VRA)** 

Probability	Very Low (1)	Low (2)	Medium (3)	High (4)	Very High (5)
Impact					
Negligible (1)	1	2	3	4	5
Low (2)	2	4	6	8	10
Noticeable (3)	3	6	9	12	15
High (4)	4	8	12	16	20
Very High (5)	5	10	15	20	25

To be used in conjunction with Section 12 defects – Investigatory Levels.

#### Note: Use of the VRA

The above table should be used by the inspector to carry out an assessment of the observed defect in relation to its risk profile. This table is built into the mobile version of AMX for use during inspections so all works required raised by inspectors will include this.

Once the defect has been identified as at, or approaching investigatory level, the inspector will determine the likelihood and severity of harm (Probability vs Impact).

Once the defect has been evaluated and given a risk score, this will be applied to the respective tables in Section 12 to set the priority of the repair if appropriate.

As stated in the "green" section of Table 2, if the defect does not meet investigatory levels and/or returns a low VRA score, no action is required for a standalone defect.

### 12. Defects – Investigatory Levels

### **Carriageways - Potholes**

Carriageway Hierarchy Depth	Local Access Road – 4b (annual)	Link Road – 4a (6 monthly)	Secondary Distributor – 3b (3 monthly)	Main Distributor – 3a (3 monthly)	Strategic Route (monthly)	
< 40mm	No action for standalone defects. Subject to assessment in section 7. See definition in Table 2.					
≥ 40mm - < 50mm	28-Day – See Note 2 – Table 2 – Defect Categorisation				Cat-1 or 1A	
,	84 Day— See Note 1- Table 2 — Defect Categorisation					
≥ 50mm - < 75mm		Cat-1 or 1A				
≤ 30mph						
≥ 50mm - < 75mm > 30mph		2 – Table 2 – Defect risation	Cat-1 or 1A			
	•	1- Table 2 – Defect risation				

Carriageway Hierarchy Depth	Local Access Road – 4b (annual)	Link Road – 4a (6 monthly)	Secondary Distributor – 3b (3 monthly)	Main Distributor – 3a (3 monthly)	Strategic Route (monthly)
≥ 75mm			Cat-1 or 1A		

#### **Pothole Definition:**

A pothole is a sharp-edged depression >300mm diameter anywhere in the carriageway where part or all of the surface layers have been removed including carriageway collapses, surrounds to ironwork and missing cats' eyes. Particular attention must be given to delamination of surfaces greater than 300mm diameter and the impact on highway users when visually risk assessing a pothole for action.

At controlled pedestrian crossings and other designated crossing points, investigatory levels shall be as for the adjacent footways. Where potholes are identified within utility reinstatements reference shall be made to Section 10 of this manual to ensure that the NRSWA Streetworks are notified.

## **Carriageways - Road Defects - Concrete / Blockwork**

Carriageway	Local Access Road –	Link Road – 4a	Secondary Distributor	Main Distributor – 3a	Strategic Route	
Hierarchy	4b	(6 monthly)	– 3b	(3 monthly)	(monthly)	
	(annual)		(3 monthly)			
Depth						
< 40mm	No actio	n for standalone defects. Si	ubject to assessment in sec	tion 7. See definition in Tab	le 2.	
≥ 40mm - < 75mm	28-Day – See Note 2 – Table 2 – Defect Categorisation  Cat-1 or 1A					
≤30mph	84 Day – See Note 1- Table 2 – Defect Categorisation					
≥ 40mm - < 75mm	28-Day– See Note 2					
> 30mph	Catego	risation		Cat-1 or 1A		
	84 Day – See Note					
	Catego	risation				
≥ 75mm			Cat-1 or 1A			

**Note:** Gaps in blockwork or expansion joints in concrete may pose a different level of impact and probability to certain road users e.g., cyclists. This must be taken into consideration when visually risk assessing any defects in relation to gap and width of a tyre on a cycle. Note tyre widths vary from 25mm upwards there is no average width. The alignment of the gap is also important i.e., is it in line with direction of travel? Gaps in excess of 25mm should be considered for a Visual Risk Assessment 84-day priority works: See section 8 b) and c) and table 2 – defect categorisation note 1.

# Footways – Surface defect in asphalt / paving and blockwork

Footway	Category 4	Category 3	Category 2	Category 1		
Hierarchy	(annual)	(6 monthly)	(3 monthly)	(monthly)		
Depth			Other (4 monthly CMK)			
< 20mm	No action for standalone defects. Subject to assessment in section 7. See definition in Table 2.					
≥ 20 mm - < 25 mm	28-Day – See Note 2 – Table 2 – Defect Categorisation					
	84 Day – See Note 1- Table 2 – Defect Categorisation					
≥ 25 mm - < 40mm		2 – Table 2 – Defect risation	Cat-1 or 1A			
	· ·	1- Table 2 – Defect risation				
≥ 40 mm			Cat-1 or 1A			

#### **Description:**

In asphalt a defect is determined as a sharp-edged depression anywhere in the footway where part or all the layers have been removed, that is likely to cause a hazard. In either paving and/or blockwork surfaces, it will be where there is a sharp edge caused by either raising and/or sinking of a unit relative to the surrounding surface. The defect will be determined as requiring a visual risk assessment when the vertical difference either approaches or exceeds 20mm or more in depth.

At controlled crossings, investigatory levels will be as for the corresponding adjacent footway.

A depression will be identified as requiring a visual risk assessment when it is approaching 40mm or more in depth and has a maximum horizontal measurement <u>less</u> than 300mm. Where potholes are identified within utility reinstatements reference shall be made to Section 10 of this manual to ensure that the NRSWA Streetworks Team are notified.

Gaps in blockwork or slabs may pose a different level of impact and probability to certain road users e.g., cyclists on shared surfaces such as CMK underpasses. This must be taken into consideration when visually risk assessing any defects in relation to gap and width of tyre on a cycle. Note tyre widths vary from 25mm upwards there is no average width. Gaps in excess of 25mm should be considered for a Visual Risk Assessment 84-day priority works: See section 8 b) and c) and table 2 – defect categorisation note 1.

## Redways – asphalt / blockwork

Redway	Category b2	Category b1				
Hierarchy	(annually)	(6 monthly)				
Depth						
< 20mm	No action for standalone defects. Subject to assessment in section 7. See definition in Table 2.					
≥ 20 mm - < 25 mm	28-Day – See Note 2 – Table 2 – Defect Categorisation					
	84 Day – See Note 1- Table 2 – Defect Categorisation					
≥ 25 mm - < 40mm	28-Day – See Note 2 – Table 2 – Defect Categorisation					
	84 Day – See Note 1- Table 2 – Defect Categorisation					

Redway	Category b2	Category b1
Hierarchy	(annually)	(6 monthly)
Depth		
≥ 40 mm		Cat-1 or 1A

#### Note:

Particular attention should be given to longitudinal cracking in asphalt surfaces. Cracks wider than 25mm should be subject to a VRA and if categorised as a hazard following the VRA, sealing the crack with an overbanding should be considered.

Gaps in blockwork may pose a different level of impact and probability to certain road users e.g., cyclists on shared redway surfaces, this must be taken into consideration when visually risk assessing any defects in relation to gap and width of tyre on a cycle. Note tyre widths vary from 25mm upwards there is no average width. The alignment of the gap is also important i.e., is it in line with direction of travel? Gaps in excess of 25mm should be considered for a Visual Risk Assessment 84-day priority works: See section 8 b) and c) and table 2 – defect categorisation note 1.

## **Carriageway - Kerbing/Channels**

CW Hierarchy	Local Access Road – 4b	Link Road – 4a (6 monthly)	Secondary Distributor – 3b	Main Distributor – 3a (3 monthly)	Strategic Route (monthly)		
Depth	(annual)		(3 monthly)				
< 40mm	No action for standalone defects. Subject to assessment in section 7. See definition in Table 2.						
≥ 40mm - < 75mm	28-Day – See Note 2 – Table 2 – Defect Categorisation						
≤30mph	84 Day – See Note 1- Table 2 – Defect Categorisation						
≥ 40mm - < 75mm	28-Day – See Note 2 – Table 2 – Defect Categorisation  Cat-1 or 1A						
> 30mph	84 Day – See Note 1- Table 2 – Defect Categorisation						
≥ 75mm			Cat-1 or 1A				

#### Note:

A defect shall be measured as either a vertical or horizontal displacement. 84-day priority works: See section 8 b) and c) and table 2 – defect categorisation note 1.

# Footway/Redway - Kerbing/Channels (Including CMK)

Footway	Category 4	Category 3	Category 2	Category 1			
Hierarchy	(annual)	(6 monthly)	(4 monthly- CMK)	(monthly)			
Depth							
< 20mm	No action for sta	andalone defects. Subject	to assessment in section	7. See definition			
≥ 20 mm - < 25 mm	28-Day – See Note 2 – Table 2 – Defect Categorisation						
	84 Day – See Note 1- Table 2 – Defect Categorisation						
≥ 25 mm - < 40mm	28-Day – See Note 2 – Table 2 – Defect Categorisation  Cat-1 or 1A						
	84 Day – See Note 1- Table 2 – Defect Categorisation						
≥ 40 mm	Cat-1 or 1A						

**Note:** In Central Milton Keynes there are a high number of large granite kerbs and channels as part of the construction of the highway. In addition, there are numerous planters constructed of large granite blocks. These units are all subject to displacement by vehicles and as such cause an obstruction in both the carriageways and the service roads/parking areas. If displaced they should be made safe as a CAT1A response, followed up by a permanent repair within either 24 hours or 28 days dependant on the visual risk assessment. 84-day priority works: See section 8 b) and c) and table 2 – defect categorisation note 1

# **Street Signs/Furniture**

Location	Grid Road	All Other Roads (Estates, Rural & Industrials)	Redways	Underpasses	СМК		
Damaged Reflective Bollard on Island		28-Day – See Note 2 – T	able 2 – Defect Cate	egorisation			
Missing Reflective Bollard/STOP/GIVE WAY sign on Island/junction	Cat-1 — see note 15						
Damaged/Missing SNP	Visual Risk Assessment – See note 8						
Damaged/Missing Bollard	Visual Risk Assessment or 28/84 Day– See note 14						
Damaged Bus Shelter/Stop	Visual Risk Assessment – See note 16						
Directional/Traffic Sign damaged	Visual Risk Assessment – See note 10						
Directional/Traffic Sign missing	See note 11						

Directional/Traffic Sign dirty/unreadable	Visual Risk Assessment – See Note 12
Chevron Sign damaged	Visual Risk Assessment – See note 13
Chevron Sign missing	28-Day – See Note 2 – Table 2, Page 25 – Defect Categorisation – also see note 13

**General Note:** The above matrix is a list of common items found on the highway, the inspector is also expected to identify any other street furniture that is damaged and identified as a hazard. Any electrical furniture should be reported to the Service Information Centre (SIC) for allocation in accordance with the Street Lighting Maintenance Code of Practice for the appropriate action.

**Note 8:** Street Name Plates (SNP) shall be assessed first by a highways inspector to determine conditions prior to any action. If the SNP is damaged to the point that it is a hazard to the public a CAT 1A response shall be raised. The enquiry should then be passed to the relevant client officer for further assessment and any necessary action as capital works in an annual programme.

#### Note 9: Not Used

**Note 10:** Directional/Traffic signs shall be assessed first by a Highways Inspector to determine conditions prior to any action. If the sign is damaged to the point that it is a hazard to the public, a CAT 1A response shall be raised. The enquiry should then be passed to the relevant client officer for further assessment and any necessary action as capital works in an annual programme.

**Note 11:** If the Directional/Traffic sign is missing the site shall be assessed first by a Highways Inspector to determine conditions prior to any action. If the sign infrastructure left is damaged to the point that it is a hazard to the public, a CAT 1A response shall be raised. The enquiry should then be passed to the relevant client officer for further assessment and any necessary action as capital works in an annual programme.

**Note 12:** A visual risk assessment shall be carried out by the inspector, if the sign is unreadable the assessment needs to account for whether this constitutes a hazard to the road user i.e. an unreadable estate local directional sign is clearly not a hazard whereas a speed limit sign outside a school would be considered a hazard. The action may well be simply to clean the sign, alternatively if the sign face has degraded and a new sign shall be required a job shall be raised under the 28/84 day priority.

Note 13: A damaged/missing chevron signs shall be assessed first by a highways inspector to determine conditions prior to any action. If the sign is damaged/missing/unreadable to highway users to the point that it is a hazard to the public a CAT 1A response shall be raised. The enquiry should then be passed to the relevant client officer for further assessment and any necessary action as capital works in an annual programme.

**Note 14:** Street bollards shall be assessed first by a highways inspector to determine conditions prior to any action. If the street bollard is damaged to the point that it is a hazard to the public a CAT 1A response shall be raised. Otherwise, job raised as '28/84 Day' category for repair/replacement. Special consideration shall be given to heavy cast iron bollards in CMK that are damaged to determine if they are stable and may be subject to falling either by their own weight or by 3<sup>rd</sup> party action.

**Note 15:** If a reflective bollard/STOP/GIVE WAY sign is missing from an island/junction a CAT1 action to 'make safe' shall be raised i.e., install an A frame with respective missing signface, 1 metre cone with a reflective sleeve to mark the island, this will then be reported to the Ringway Hub who will raise a job in accordance with the street lighting Code of Practice.

**Note 16:** Any bus shelter identified as damaged shall be immediately reported to Passenger Transport team. If it is a hazard to the public the area must be made safe pending instruction from the Client. All records to be provided including photographs and asset record number of bus shelter.

#### Flooding/Drainage

See Emergency Response Flooding/Drainage - Code of Practice for Drainage Maintenance and Highways Emergency Response Manual

## 13. Examples of Prioritisation of Defects

### CAT - 1A (2 Hours)



Hazards presenting an immediate and imminent hazard or risk to road users. Immediately make safe or repair within 2 hours. Such defects will include (this list is not exhaustive):

### **Carriageway**

- Clearing up after RTCs
- Clearance of debris or oil
- Serious subsidence or collapse of road
- Flooding over a large area
- Missing ironwork
- Seriously damaged traffic signals
- Damaged street bollards
- Missing or seriously damaged guardrail
- Potholes see matrix potholes section 12 and Table 3 (VRA)
- Redway/footway bollards missing (where lockable bollard flaps aren't able to make safe the hazard)
- Rapid deterioration of structure/ trees
- Hazardous obstructions left on highway

#### **Footways**

- Exposed electrical wiring on street furniture
- Rapid deterioration of structure/ trees
- Damaged street bollards/bus shelter

#### **Verges**

Hazardous obstructions left on highway


#### **Flooding**

• See Code of Practice for Drainage Maintenance

Note – All jobs identified in this category will be phoned directly through to the SIC by the Highways Inspector, who will dispatch a gang to attend as soon as possible. The Highways Inspectors and SIC will coordinate the appropriate recording of the detail in AMX as per this guidance.

Emergency Calls relating to defects will be dealt with in accordance with MKC "Emergency Procedures Manual".

## CAT – 1 (24 Hours)



#### **Carriageway**

- Potholes see matrix potholes section 12
- Abrupt level difference see matrix road defects section 12
- Missing unlit bollard on island
- Damaged street bollards
- Hazardous obstructions left on highway

#### **Footways**

- Collapse or serious subsidence
- Damaged street bollards/bus shelter
- Missing ironwork
- Seriously damaged street furniture or fencing
- Abrupt level difference/surface defects see matrix footways section 12.

### **Redways**

- Serious subsidence or collapse of redway
- Flooding over a large area
- Missing ironwork.
- Surface defects see matrix redways section 12.

#### **Verges**

- Edge deterioration or rut over 150mm in Cat 1 and 2 footways only.
- Verge damage likely to cause a hazard or risk, taking in to account the location and density of use by the public for guidance.
- Hazardous obstructions left on highway

#### **Flooding**

• See Code of Practice for Drainage Maintenance

#### CAT – 28 Day (28 calendar days)



#### **Carriageways**

- Missing or dislodged kerbs in carriageway
- Potholes see matrix potholes section 12
- Abrupt level difference see matrix road defects section 12
- Damaged unlit bollard on Island
- Damaged street bollards
- Signs that if missing/unreadable will constitute a hazard

#### **Footways**

- Abrupt level difference see matrix footways section 12
- Damaged street bollards/bus shelter
- Missing bollards where flap is able to make safe, but bollard needs replacing
- Surface defects see matrix footways section 12

#### **Redways**

- Abrupt level difference see matrix redways section 12
- Missing bollards where flap is able to make safe, but bollard needs replacing
- Surface defects see matrix footways section 12

### **Flooding**

• See Code of Practice for Drainage Maintenance

## CAT – 84 Day (84 calendar days)

Defects presenting a lower level of hazard or risk. Such defects will include:

#### **Carriageways**

- Large Surface defects/patches section 12
- Damaged surface crazing, deformation, rutting, unevenness section 12
- Abrupt level difference see matrix road defects section 12
- Longer section of kerbs/channels likely to deteriorate if not repaired section 12
- Damaged street furniture section 12

#### **Footways**

- Large surface defects/patches section 12
- Damaged street furniture section 12

#### **Redways**

- Large surface defects/patches section 12
- Damaged street furniture section 12

# **Appendix B – Job Defect Number Matrix**

Note – some items in this table are under review and an updated Code of Practice will be issued when confirmed

	ī		Milton Keynes Defect Repair Matrix				
Network Position	Surface Material	Defect Type	Repair Solution	Max Size for Defect	Notes	Job Type	SoR Re
	Soil and Grass			Not exceeding 15 lin m	Please state volume to be filled		
Verge	Siding Out Encroachment onto footway		Cut back and remove soil and vegetation	Not exceeding 15 lin m		PR*	Planned
Grips	Grips	Blocked Grip	Cut grip, stating width - 300/500/1000mm	Individual			
	Bitmac (Footway)	Surface Defect	Clean, cut vertical joint, fill with surface course, compact and overband	Individual up to 2m <sup>2</sup> or within 20 lin. m			
	Bitmac (Redway)	Surface Defect	Clean, cut vertical joint, fill with surface course, compact and overband	Individual up to 5m <sup>2</sup> or within 20 lin. m			
	Slabs	Uneven, loose, rocking or low	Take up and relay to correct level	Individual or up to 6 adjacent			
	Siabs	Missing	Renew to match existing	Individual or up to 6 adjacent			
	CMK Slabs	Missing,uneven, loose, rocking or low	Renew to match existing	Individual slab or up to 6 slabs within 10 m2			
Footusy Bodysov	Insitu Concrete	Cracks (as per COP)	Clean and repair with mortar material	Individual		RMFB. RMRB.	' I DEFOOT
Footway,Redway, Cycle Tracks	mata concrete	Surface Irregularities	Clean and repair with mortar material	Individual		RMFW, RMRW	
Cycle Tracks	Block Paving	Uneven, loose, rocking or low	Take up and relay to correct level	Up to 1m <sup>2</sup>		RIVIFW, RIVIKW	
		Missing	Renew to match existing	Up to 1m <sup>2</sup>	State colour and thickness		
	Brick Paving	Uneven, loose, rocking or low	Take up and relay to correct level	Up to 1m²			
		Missing	Renew to match existing	Up to 1m <sup>2</sup>	State exact size and colour		
		Uneven, loose, rocking or low	Take up and relay to correct level	Up to 1m²	State sizes to be handled		
	Missing		Renew to match existing Up to 1m <sup>2</sup>				
Carriageway	Bitmac	Surface Defect	Clean, cut vertical joint, fill with surface course, compact and overband	Individual up to 2m <sup>2</sup> or within 20 lin. m		RMCB	DECARR
	Concrete	Broken, rocking or depressed or missing	Renew and reinstate as necessary	Individual or 5 within 20 lin. m			
	Concrete	Chipped or damaged but still sound	Clean and repair with mortar material	Individual or 5 within 20 lin. m			
Kerbs, Edgings and	Natural Stone	Rocking or depressed	Relay exisiting	Individual or 5 within 20 lin. m		DN4E\A/ DN4D\A	V DEKEEDCH
Preformed Channels	Natural Storic	Broken or missing	Renew and reinstate as necessary	Individual or 5 within 20 lin. m		KIVIF VV, KIVIK VV	
	Granite Setts	Rocking or depressed	Renew and reinstate as necessary	Up to 1 lin. m			
	Granite Setts	Broken or missing	Clean and repair with mortar material	Up to 1 lin. m			
		Broken or missing gully cover	Renew and reinstate as necessary	Individual			
	Road Gullies	Settled or rocking gully frame	Reset using rapid set mortar	Individual			
Covers, Gratings,		Broken gully frame	Renew frame and cover and reinstate as necessary	Individual		RMCB, RMFB,	DEBOXES
Frames and Boxes		Broken or missing cover	Renew and reinstate as necessary	Individual		RMRB	DEBUXE
	Manholes	Settled or rocking manhole frame	Reset using rapid set mortar	Individual			
		Broken manhole frame	Renew frame and cover and reinstate as necessary	Individual			

# **Appendix C – Defect Abbreviations**

Description	Abbreviation	Description	Abbreviation
City centre slabs ,		Kerbs / Radius add in	
silver granite on city	CC	the discription the type of	KRB/ RAD
centre bedding		kerbs i.e HB = Half batt	
Redway closure	RWC	Gully covers and frames	GUL
Footpath Closure	FPC	Carriageway	CW
Footway Closure	FWC	Roundabout Closure	RBTC
High speed Road			
closure, I. for inside	101/100	Roundabout	RBT
closure -O. for out	LCI / LCO	Roundabout	KBI
side closure			
Road Closures	RC	Concrete edging or Wooden Edging	CEG/WEG
Stop -Stop boards	SSB	Portable Traffic Lights for 2/3/4	2WL/3WL/4WL
Stop and Go boards	SGB	Take up and Relay	TURL
Tarmac Footway (6mm or 10mm)	TF6/TF10	Take up and replace	TURP
Tarmac Redway 6mm	RTF6	Take up and relay manhole covers	TURM
Block Carriageway	BCW	Give and Take System	GT
Block Footway	BLF	Priority Boards	PB
Redway	RWY	Stats Required	SR
Cone off Night Before	CNB	soil and seed for city centre	SAS
		Granite kerbs and Granite setts	
No TM Required	NTM	, This can also be used for	GK/GS/GB
		Granite Blocks	
Hot Roll Asphalt	HRA	Heavy lifting Equipment	HLFT
Dense Bituminus Macadam	DBM		
High Stone Content Asphalt	HSCA		

