

B526 NORTH OF STOKE GOLDINGTON

Update November 2016

REPAIR TO CARRAGEWAY

We have concluded our investigation works to the undermining of the road north of Stoke Goldington, caused by localised animal activity in the area.

Due to the exceptional voids and tunnelling under the road surface, we have concluded that the safest option is to close the road, for both crews and members of the public safety.

This will allow us to carry out a large deep excavation to a localised section of carriageway in order to effect a full depth repair to the road.

The road closure will commence from 09:30 on the 14th Nov 2016 until approx. 17:30 on the 24th Nov 2016 **(Please note the closure will be in operation 24 hours a day).**

No vehicles at all will be allowed to pass day or night down on this section of road (except for property access under a controlled gate), while the carriageway repairs are being carried out over this period.

We thank you for your cooperation in this matter and have attached a map of the area (on website) under excavation and also a diversion route while works are carried out.

If you see that traffic control measures are damaged or interfered with please contact Milton Keynes council service centre on

01908 252353 Monday to Friday 9.00 am to 17:15 pm

01908 226699 Out of hours emergency telephone

We apologise again for the disruption caused by this situation and will work swiftly to rectify this matter as soon as we can.

1st November 2016